SAN JACINTO SPECIAL UTILITY DISTRICT 70 CHURCH AVE COLDSPRING TX 77331 936-653-4384

7/2019

San Jacinto SUD has violated the monitoring and reporting requirements set by Texas Commission on Environmental Quality (TCEQ) in Chapter 30, Section 290, subchapter F. Even though these were not emergencies, as our customers, you have the right to know what happened and what we did to correct these situations.

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During July 2018 and December 2018, we did not complete all monitoring or testing for Water Quality Parameters and therefore cannot be sure of the quality of your drinking water during that time.

The table below lists the contaminants we did not properly test for during the last year, how often we are supposed to sample, how many samples should have been taken and the date the follow-up samples were taken.

Contaminant	Required Sampling Frequency	Number of Samples taken	When Samples should have been Taken	When Samples were taken
Water Quality	quarterly	0	July-December 2018	January 2019

What is being done? We are working to correct the problem. For more information contact San Jacinto SUD at 936-653-4384 or 70 Church Ave Coldspring TX 77331.

Please share this information with all other people who drink this water, especially those who may not have received this notice directly (i.e. people in apartments, nursing homes, schools and businesses. You can do this by posting this notice in a public place or distribute copies by hand or mail.

This notice is being sent to you by San Jacinto SUD Public Water System # 2040033 (7-2019)